



Part of the Energy Queensland Group



Operational Update

Safety Awareness

Issue # C-0004 – 22/07/2019

Target Audience:

Consultants, Accredited Service Providers

Introduction:

This Update is to highlight the need for Accredited Service Providers to be vigilant in their performing their safety obligations.

Reinforcement is required for the following;

Job Safety Assessment

- There have been some recent cases where Accredited Service Providers have **not** completed a Job Safety Assessment prior to starting work.

Construction Authority

- Accredited Service Providers **not** performing work related to requirements identified in issued Construction Authority. This has included not applying earths as set out in the issued Construction Authority.
- Accredited Service Providers not applying working earths on O/H 11KV mains where there are no visual operator earths when working under an A/P.

It is imperative that all Accredited Service Providers reinforce awareness to these critical safety requirements with their staff.

For more information contact:

[E-mail contestable@energyq.com.au](mailto:contestable@energyq.com.au)